

	
Name of supplier	KW-Commerce GmbH
	Jägerstr. 41
Address of supplier	10117 Berlin
	Deutschland
Model Identifier and other applicable models below	40590.01
40590.01	1/ 0 013
40590.35	d. Elisko
40590.73	71.0000
40590.91	29 October 2021
40590.81	Katharina Zelisko
	Business Unit Director

Specific precautions that shall be taken when the model is assembled, installed, maintained or tested

See user manual for normal use. For testing, pay special attention to the contained Lithium battery. Opening

Disposal recommendations at the end of the light source's life time (Directive 2012/19/EU)

Translations and national adaptations are included in the user manual of the item, supplied with the light source or its containing product.

The Waste Electrical and Electronic Equipment (WEEE) Directive aims to minimise the impact of electrical and electronic goods on the environment, by increasing re-use and recycling and by reducing the amount of WEEE going to landfill. The symbol on this product or its packaging signifies that this product must be disposed separately from ordinary household wastes at its end of life. Be aware that this is your responsibility to dispose of electronic equipment at recycling centers in order to conserve natural resources. Each country should have its collection centers for electrical and electronic equipment recycling.

For information about your recycling drop off area, please contact your related electrical and electronic equipment waste management authority, your local city office, or your household waste disposal service.

Contained Light Source(s)	Pieces
51527A	1

Contained Separate Control Gear(s)	Pieces
NA	

Light Sources can be replaced by end-user or qualified persons?

Non-replaceable

Separate Control Gears can be replaced by end-user or qualified persons?

NΑ

Instructions on how to remove lighting control parts and/or non-lighting parts, if any, or how to switch them off or minimise their power consumption during light source testing

This is a legacy product, not designed to allow replacing the light source. The light source includes a lithium battery. Do not open the light source.

The lithium battery shall be disconnected from circuits in the light source.

In order to minimise the effect of battery charging on measurements, ensure full charge of the battery (5 hours) before starting the test.